

# PM 22 Ø 22 mm, Metal

Parameter	1-stage	2-stage	3-stage
Perm. output torque $T_{AB}$ (Appl. factor $C_B = 1.0$ )	0.6 Nm	0.7 Nm	0.8 Nm
Gearbox efficiency, approx.	0.90	0.80	0.70
Max. backlash	1.5 °DEG	2.0 °DEG	2.5 °DEG
Recommended initial speed	6,000 U/min	6,000 U/min	6,000 U/min
Min. Operating temperature	-30 °C	-30 °C	-30 °C
Max. Operating temperature	+120 °C	+120 °C	+120 °C


## Current reduction ratios i rounded

1-stage	2-stage	3-stage
4:1 (3.71)	14:1 (13.73)	51:1 (50.89)
4:1 (4.29)	16:1 (15.88)	59:1 (58.86)
5:1 (5.18)	18:1 (18.37)	68:1 (68.07)
7:1 (6.75)	19:1 (19.20)	71:1 (71.16)
	22:1 (22.21)	79:1 (78.72)
	25:1 (25.01)	93:1 (92.70)
	27:1 (26.85)	95:1 (95.18)
	29:1 (28.93)	100:1 (99.51)
	35:1 (34.98)	107:1 (107.21)
	46:1 (45.56)	115:1 (115.08)
		124:1 (123.98)
		130:1 (129.62)
		139:1 (139.14)
		150:1 (149.90)
		169:1 (168.85)
		181:1 (181.25)
		195:1 (195.27)
		236:1 (236.10)
		308:1 (307.55)

Output side with ball bearing (2Z)	1-stage	2-stage	3-stage
Max. load, radial (10 mm from flange)	25 N	35 N	50 N
Max. load, axial	10 N	15 N	15 N
Max. perm.fitting pressure	80 N	80 N	80 N
Weight approx.	43 g	59 g	75 g

Gearbox length in mm	1-stage	2-stage	3-stage
Length l*	24.25 ± 0.5	32.4 ± 0.5	40.6 ± 0.5

\* The minimum length is only possible with an optimal attachment to the motor, the actual length we like to determine for you.



All figures are approximate values.

Variations are possible and may arise for example due to non-standardized inspection and measurement methods. For more detailed information, please contact us directly. The company always reserves the right to make technical modifications. For current status, please consult [www.imsgear.com](http://www.imsgear.com)